






Features

- Fast f/2.0 aperture
- Precise manual focusing
- Robust full-metal construction
- Continuous aperture setting or click stop
- For industrial cameras up to sensor sizes of 24x36 mm or 41 mm line sensors
- High optical performance both at infinity and at 1:5.3 scale
- Features special screws to fix focus and aperture settings even in rough situations

Camera MountsAvailable with F mount or M42 screw mount



Technical Specifications




Focal length	35 mm
Aperture range	f/2 – f/22 (1/ 2 stop intervals or continuous)
Number of elements / groups	9/7
Min. working distance	300 mm (0.98 ft.) — ∞
(object to sensor)	
Min. free working distance	180 mm (0.59 ft.) — ∞
Angular field* (diag. / horiz. / vert.)	62 / 53 / 37°
Max. diameter of image field	43 mm (1.7")
Flange focal length	F-Mount: 46,5 mm (1.8");
	M42-Mount: 45,5 mm
Coverage at close range*	area: 127 x 190 mm (5.0 x 7.5")
	line: 217 mm (8,5")
Image ratio at close range	1:5.3
Filter-thread	M58 x 0.75
Weight	716 g (1.6 lbs.)
Camera mount	F bayonet, M42

^{*} referring to 35 mm format




Relative Illuminance*



The relative illumination shows the decrease in image brightness from the image center to the edge in percent.

- __ f-number 2
- --- f-number 4

Relative Distortion*




The relative distortion shows the deviation of the actual image height from the ideal one in percent.

^{*}Data for infinite focus setting




MTF Charts*



The Modulation Transfer (MTF) as a function of image height (u) and slit orientation (sagittal, tangential) has been measured with white light at spatial frequencies of R = 10, 20 and 40 cycles/mm.

f-number 2

- ___ Sagittal
- ... Tangential




f-number 4 ___ Sagittal ... Tangential


^{*}Data for infinite focus setting



Spectral Transmission







M42 Mount for 45,5 mm Flange Focal Distance

The diameter of the camera/lens adapter must not exceed 55 mm at the lens side!